

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)  
(Re. G.O. Ms. 20/70/PWD Dt. 23-01-1970)

Name of the School

ST. XAVIER'S CENTRAL SCHOOL  
MANGALAMDAM, PALAKKAD, ALATHOR  
MANGALAMDAM

1. Name of the Officer

2. Location

3. Period for which the certificate is issued

2023-2024

4. Types of building

RCC

5. Nature of defect if any

a) Foundation and basement

b) Superstructure

c) Doors and windows

d) Wood work wrought and put up

e) Roof

f) Flooring

g) Miscellaneous (Cracks if any)

CLASS ROOM

L B H (m)

NIL CELLAR FLOOR 24.55 13.66 3.60

GF 49.48 10.60 3.60

FF 49.48 10.60 3.60

6. Any Major defects notices which will render the building unsafe in any manner

No.

7. Whether maintenance works have been done properly

Yes

8. Whether the structure is sound or not for conducting classes

Yes, The structure is sound under normal wind and weather conditions

Note:- 1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure or flood etc.  
2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

## CERTIFICATE

Certified that the School was inspected by me on 26-05-2023  
and found to be fit / unfit to conduct classes for the period 2023-2024  
for the reason stated above.

Place: Vondazhy

(Seal)

Date: 26/05/2023



Signature  
Asst. ENGINEER  
LSGD SECTION  
VONDZHY GRAMPANCHAYAT