TO BE FILLED BY THE INSPECTING OFFICER

(Assistant Engineer)

Name of School St. Xavier's Central School, Mangalam dam 1 Name of Officer Siji Jose, Assistant Engineer LSGD Section, Vandazhy Grama Panchayath Location
 Period which the certificate is issued Mangalam Dam 2024-25 RCC Building 4 Type of Building Cellar floor - 24.55m x13.66m x3.60m Ground floor - 49.48m x10.60m x3.60m 5 Nature of defect if any First floor - 49.48m x10.60m x3.60m a) Foundation and Basement b) Super Structure NBI c) Doors and Windows d) Wood work Wrought & put up e) Roof f) Flooring g) Miscellaneous 6 Any Major defects noticed which will render the building unsafe in any manner Whether maintenance work have been

8 Weather the structure is sound for conducting classes under normal weather condition. Note: (1) The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to flood etc.

(2) Any additional observations, if deemed necessary for the certificate may be furnished separatly with the certificate.

Yes

Certified that the school was inspected by me on 28/05/2024 and found fit to conduct classes for the period 2024-25 for the reasons stated above.

Place: Vandazhy Date 28/05/2024 Signature Syllose

The Structure is sound for conduct classes

ASST. ENGINEER LSGD SECTION
VANDATHY CRAMA PANCHAYAT

