

**TO BE FILLED BY THE INSPECTING OFFICER**

(Assistant Engineer)

SFS / AR VDY / 14 / 2025 - 26, Dt: 26/6/25

- Name of School : St.Xavier's Central School, Mangalam dam
- 1 Name of Officer : Haridas R, Assistant Engineer,  
LSGD Section, Vandazhy Grama Panchayath
- 2 Location : Mangalam Dam
- 3 Period which the certificate is issued 2025-26
- 4 Type of Building : RCC Building
- 5 Nature of defect if any : 

a) Foundation and Basemer	:	Nil
b) Super Structure	:	
c) Doors and Windows	:	
d) Wood work Wrought & put up	:	
e) Roof	:	
f) Flooring	:	
g) Miscellaneous	:	
- Cellar floor - 24.55m x13.66m x3.60m  
Ground floe - 49.48m x10.20m x3.60m  
First floor - 49.48m x10.20m x3.60m
- 6 Any Major defects noticed which will render the building unsafe in any manner : No
- 7 Whether maintenance work have been done : Yes
- 8 Weather the structure is sound for conducting classes : The Structure is sound for conduct classes under normal weather condition.

Note (1) The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to flood etc.

(2) Any additional observations, if deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me on 25/06/2025 and found fit to conduct classes for the period 2025-26 for the reasons stated above.

Place: Vandazhy  
Date : 26/6/2025

Signature



*[Handwritten Signature]*  
HARIDAS, R  
PEN : 370153  
ASSISTANT ENGINEER  
LID & EW SECTION  
VANDAZHY GRAMA PANCHAYATH  
678 709